

## Rumrill, Nancy

---

**From:** Jennifer Saran <JenniferSaran@florencecopper.com>  
**Sent:** Wednesday, September 29, 2021 4:56 PM  
**To:** Rumrill, Nancy  
**Cc:** greenslade.maribeth@azdeq.gov; Brent Berg; MNicholls@haleyaldrich.com  
**Subject:** revised Attachment C  
**Attachments:** ATT00001.txt; 2021-0929\_Attachment C\_rev6.pdf

Good afternoon,

Please find attached a revised version of Attachment C in support of our application for an Underground Injection Control (UIC) Permit submitted to the EPA on October 4, 2019. This version includes the following changes:

1. Updated Figure C-1 to show the sacrificial ACD installed on 2 ISCR wells.
2. Inserted updated Figure C-4c.
3. Added Figures (C-5 through C-8) previously submitted to EPA showing construction details for all UBFU and LBFU monitoring wells, including ACD contingency monitoring wells, USDW monitoring wells, and the fault monitoring wells.
4. Added text to Section C.2.5.3 clarifying that ACDs will be installed on USDW monitoring wells and fault monitoring wells – and that ACDs will not be installed on M72-UBF, M73-LBF or the ACD contingency monitoring wells.
5. Added text to Section C.2.5.3 stating all ACDs will be installed as shown on Figure C-4.

Please let me know if you have any questions, or need additional information.

Thanks,  
Jennifer

**Jennifer Saran** Environmental, Health and Safety Manager



Florence Copper Inc.  
1575 W. Hunt Highway Florence AZ USA 85132  
C 480-532-0108 T 520-316-3707 F 520-374-3999  
E [jennifersaran@florencecopper.com](mailto:jennifersaran@florencecopper.com) Web [florencecopper.com](http://florencecopper.com)

**SAFETY – Own it. Practice it. Share it.**  
**#FLORENCECOPPERSTRONG**

---

### "Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."